

## Serial upgrade procedure: TCGXX-E & TCGXX-G

This upgrade process applies to the following:

Clock Hardware Revision	Your Current Firmware Revision	Latest Firmware Revision
TCGXX-G	F:2.XX	F:2.25r2
TCGXX-E	F:1.00 and above	F:2.25r2
TCGXX-E	E:1.00 and above	E:1.13
TCGXX	D:09.001 and above	D:10.13

**WARNING: Please double check that your current firmware version matches the above table. If you are unsure please contact [support@tekroninternational.com](mailto:support@tekroninternational.com), we will get back to you within 1 working day.**

### Pre-update requirements

You will require the following:

- PC with a Windows operating system (2000, XP, Vista or Windows 7).
- A PC with a **BUILT IN SERIAL PORT. DO NOT USE A USB TO SERIAL CONVERTER.**
- Power supply rated at the recommended voltage for the unit.
- DCE Serial Cable

### Serial upgrade procedure

**DO NOT USE A USB TO SERIAL CONVERTER TO COMPLETE THIS UPGRADE.**


1. Disconnect power and then disconnect all outputs and the antenna from the unit.
2. Plug the unit into your PC using a DCE Serial cable.
3. Plug in the power.
4. Open The serial upgrade application.
5. The tool will automatically scan the PCs COM ports, until it identifies the connected clock.

**NOTE:** If the tool scans for more than 1 minute, without finding a clock, please check the following:

- a. That the TCG is powered up, and the LEDs on the front panel are flashing
- b. That a DCE serial cable is plugged into the TCG that is being upgraded
- c. Finally, close the upgrade tool, and power cycle the unit, before trying again.




- Click "OK" to begin the update process.



- The upgrade tool should start uploading the new firmware to the clock. Please **DO NOT UNPLUG THE CLOCK FROM THE PC UNTIL THE UPGRADE HAS BEEN COMPLETED**.
- If the firmware upgrade is successful, the upgrade tool will remain open, and report "TCG Upgrade Finished".
- Once the upgrade is successful, the upgrade tool can be closed.



- UPGRADE FAILED:** If the upgrade tool reports "Upgrade Failed" at any step, please complete the following:



- Click the "Close" button on the TCG Update Tool
- Power cycle the clock, and wait for it to reboot.
- Re open the Upgrade tool, and complete steps 1 through 8.
- If the LCD display is blank, due to a partial upgrade, the upgrade tool may fail to automatically detect the correct com port. The correct com port will need to be manually selected when the settings menu appears.
- If the upgrade continually fails, please contact **Tekron** for further assistance.